

.

From: Nassif, Julianne (DPH)
Sent: Tuesday, June 23, 2009 9:26 AM
To: Lawler, Michael (DPH); Salemi, Charles (DPH)
Subject: RE: failure of hood, room 363

I will check w/ John Nickerson to see if something can be done.
Julie

From: Lawler, Michael (DPH)
Sent: Tuesday, June 23, 2009 9:25 AM
To: Nassif, Julianne (DPH); Salemi, Charles (DPH)
Subject: failure of hood, room 363

FYI

B&V Testing, Inc. tested the hood in room 363 June 15 and failed it for certification. It did not achieve an air turnover rate of 80 linear feet per minute when the sash was at working height.

Currently three of our five hoods are out of commission, leaving the devoted marijuana testing hood and one other general purpose chemical hood.

B&V will generate a report to Howard Lefkin and I will have the hood status placed on the next Facility's meeting agenda.

My guess is we will have no further action on the matter until the Tower energy audit is complete and the new electricity distribution is determined.